## Dear Requestor,

Hereford and Worcester Fire and Rescue Service submit incident reports to the Home Office's Incident Recording System. At present, there is no option to capture that a fire was attributed to the equipment you have specified. Therefore, a free-text search of incident recordings between 01/04/2019 and 31/05/2024 has been conducted using search criteria such as 'solar', 'battery' or 'heat pump' etc.

We have been unable to answer questions 5-7 as this information is not recorded by the Service. A table with the requested details has been provided in answer to questions 1-4.

- 1. Number of incidences attributed to: a. Solar PV b. Battery Storage System c. Heatpump (Airsource)
- d. Heatpump (ground source) e. Wind turbine f. Electric Vehicle Charging Equipment
- 2. Number of injuries caused by the incidences in question 1.
- 3. Number of deaths caused by the incidences in question 1.
- 4. What was the cause of the incidences (based on IRS categories)? Faulty Appliances and Leads Misuse of Equipment or Appliances Careless handling of fire or hot substances Deliberate Faulty fuel supplies Placing articles too close to heat Playing with fire Other (please state)

Year	Incident Attributed To	IRS Cause Recording	Injuries	Deaths
		Fault in equipment or	0	0
2020	Solar PV	appliance		
		Fault in equipment or	0	0
2020	Solar PV	appliance		
2021	Solar PV	Overheating, unknown cause	0	0
2024	Solar PV	Faulty fuel supply - electricity	0	0
2024	Solar PV	Faulty fuel supply - electricity	0	0
	Battery Storage System	Fault in equipment or	0	0
2023	(Lead Acid)	appliance		
	Heat Pump (Ground	Fault in equipment or	0	0
2022	Source)	appliance		
	Heat Pump (Unspecific	Fault in equipment or	0	0
2023	Source)	appliance		
	Electric Vehicle Charging		0	0
2023	Equipment	Faulty fuel supply - electricity		